
City of Baltimore Wet Smoke and Dyed	Page 1 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/22/2009
Test to be performed:  Smoke Dyed Water X	Ground Condition:  Dry ☑ Damp ☐ Wet ☐	Supervisor: JAW
Manhole_ID: S09I018MH	Test ID: <u>D1032-008003</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S09I030MH
23.20000076			Dye Test Visible	@ IR, 1/2 GPM
23.20000076	10		Infil Runner	@ jt
27.79999924			Dye Test Visible	@ IR, 1/8 GPM
27.79999924	08		Infil Runner	@ jt
30.60000038			Dye Test Visible	@ IR, 1/4 GPM
30.60000038	04		Infil Runner	@ jt
30.60000038			Dye Test Visible	@ IR, 1/4 GPM
30.60000038	09		Infil Runner	@ jt
38.09999847			Abandoned Survey	NO MORE DYE VISIBLE

City of Baltimore Wet Smoke and Dyed	Page 2 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/22/2009
Test to be performed:  Smoke Dyed Water X	Ground Condition:  Dry ✓ Damp □ Wet □	Supervisor: JAW
Manhole_ID: S09I018MH	Test ID: <u>D1032-008003</u>	Notification Made: NA (Residents, Fire, 311)